



U.S. Department
of Transportation

**Federal Aviation
Administration**

**Transport Airplane Directorate
Los Angeles Aircraft
Certification Office**

3960 Paramount Boulevard
Lakewood, California 90712-4137

January 18, 2008

Mr. Joseph McGarvey, Agent for:
Airwolf Aerospace, LLC
15369 Madison Road
Middlefield, Ohio 44062

Reference: AMOC request to FAA, received January 14, 2008

Dear Mr. McGarvey,

Approval of Alternative Method Of Compliance (AMOC) for AD
2007-26-12

We concur that installation of Airwolf Aerospace, LLC Rotor Blade Protective Tape per Supplemental Type Certificate (STC) SR02491CH provides an acceptable level of safety in accordance with paragraph (d) of this AD.

This STC may only be installed after compliance with paragraphs (a) and (b) has been accomplished. Thereafter, the preflight check required by paragraph (c) of the AD is not required provided the following actions are performed:

1. At every 100 hour or annual inspection, whichever occurs first, inspect the condition of the protective tape in accordance with Airwolf Aerospace, LLC Instructions for Continued Airworthiness, Report RBPT-100-ICA, Revision: 0, dated 6/18/07, or later FAA accepted revision.; and
2. Update the applicable "Pilot Operating Handbook and FAA Approved Rotorcraft Flight Manual" to include revisions dated 20 April 2007, and later revisions.

Note: The approval of STC SR0249CH supersedes the restriction to the installation of "blade tape (anti-erosion tape)" exists in the applicable Robinson Maintenance Manuals.

This AMOC may be copied and distributed to any interested party.

If you have any questions regarding this approval, please contact Mr. Fred Guerin at (562) 627-5232, or Mr. Eric Schrieber at (562) 627-5348.

Sincerely,



Kevin Hull
Manager, Los Angeles Aircraft Certification Office